



# HA139458 [CREE LED Hi-Lo Beam Light, 4200 Lumens]

## Instruction Guide

1. Disconnect wiring from original light
2. Remove original light and bezel from machine
3. Remove OE light from rubber bezel
4. Install new Hy-Cap light into rubber bezel
5. Replace bezel and light onto machine
6. Join electrical connectors
7. If light has no power, confirm that connector on machine is wired like photos shown

